



Extinguisher Certificate of Inspection

Site Address	Equipment Serviced			New Extinguishers Supplied		Exchange/Refill Supplied		New Equipment Supplied		Additional Items	
St Peters Court Walcott Road Bacton NR12 0LR	Equipment	Qty	NC	Equipment	Qty	Equipment	Qty	Equipment	Qty		Qty
	6L Foam	3	1	6L Water	1	None		Sign - Water	1	O-Rings	6
	2kg Co2	4								Tamper Seals	7
	Fire Blanket	1								Gauge Tests	3
										Fixing	
										Environmental Disposal	1

Date
02/12/2024

Signed the logbook?
No

Technicians Comments/Recommendations

Where applicable Technicians are being advised to change foam extinguishers to waters where there is no flammable liquid risk present, this is due to phasing out of foam extinguishers which contain the PFAS chemical.

I being the competent person responsible for the servicing of the equipment described above, certify that other than non-conforming items recorded, all equipment has been serviced and inspected in accordance with BS 5306 part 3. Unless otherwise stated, all non-conforming equipment has been rectified via repair or replacement where relevant.

Technician Name Ellie Soanes

Technician Signature

This is to certify that the service detailed in this document is satisfactory and I/we hereby agree to pay. **RETENTION OF TITLE:** All goods and service/repairs parts will remain the property of Soanes Fire Ltd until all amounts have been paid in full. The customer will remain bailee until payment.

Customer Name Bob Collins